


**ECAC CEP Explosive Detection Systems (EDS) equipment (ECAC/EU expired standards <sup>(1)</sup> only). Update 30 June 2025**

Manufacturer	Equipment		Standard	Notification
	Designation	Configuration <sup>(2)</sup>		
<b>L-3 Communications</b>	<b>MVT HR</b>	<i>Hardware configuration:</i> MVT-HR <i>Detection Algorithm:</i> V7.3.2 <i>Auxiliary Software:</i> v.5.9.0 <i>Auxiliary Hardware:</i> No tray	<b>1</b> <sup>(3)</sup> (ECAC/EU expired)	14/05/2013



**ECAC CEP Explosive Detection Systems (EDS) equipment (ECAC/EU expired standards (1) only). Update 30 June 2025**

Manufacturer	Equipment		Standard	Notification
	Designation	Configuration <sup>(2)</sup>		
<b>Rapiscan</b>	<b>RTT80</b>	<i>System Hardware:</i> RTT 80 <i>Detection Algorithm Version:</i> 1.0.1 <i>Auxiliary Software:</i> v.6.0.3 <i>Auxiliary Hardware:</i> No tray	<b>1</b> <sup>(3)</sup> (ECAC/EU expired)	08/10/2010
<b>Rapiscan</b>	<b>MVXR 5000</b>	<i>Hardware:</i> MVXR5000-Mk4 <i>Detection Algorithm:</i> 6.3 <i>Auxiliary Hardware:</i> No Tray <i>Hardware:</i> MVXR5000-Mk4	<b>2</b> <sup>(4)</sup> (ECAC/EU expired)	18/04/2012



**ECAC CEP Explosive Detection Systems (EDS) equipment (ECAC/EU expired standards <sup>(1)</sup> only). Update 30 June 2025**

Manufacturer	Equipment		Standard	Notification
	Designation	Configuration <sup>(2)</sup>		
Smiths Detection	<b>HI-SCAN 10080 EDX-2is</b>	<i>Hardware</i> HS 10080 EDX-2is <i>Detection Algorithm</i> 06-50-09 <i>Auxiliary Software:</i> ES-03-10-1-89-01 <i>Auxiliary Hardware:</i> No tray	<b>1</b> <sup>(3)</sup> (ECAC/EU expired)	03/09/2012
Smiths Detection	<b>HI-SCAN 10080 EDtS</b>	<i>Hardware:</i> HS 10080 EDtS <i>Detection Algorithm:</i> 02-51-09 <i>Auxiliary Hardware:</i> No Tray	<b>2</b> <sup>(4)</sup> (ECAC/EU expired)	23/11/2009
Smiths Detection	<b>HI-SCAN 10080 EDtS</b>	<i>Hardware:</i> HS 10080 EDtS <i>Detection Algorithm:</i> 07-32-09 <i>Auxiliary Hardware:</i> No Tray	<b>2</b> <sup>(4)</sup> (ECAC/EU expired)	19/11/2013
Smiths Detection	<b>HI-SCAN 10080 EDX-2is</b>	<i>Hardware:</i> HS 10080 EDX-2is <i>Detection Algorithm:</i> 05-80-09 <i>Auxiliary Hardware:</i> No Tray	<b>2</b> <sup>(4)</sup> (ECAC/EU expired)	05/10/2010
Smiths Detection	<b>HI-SCAN 10080 EDX-2is</b>	<i>Hardware:</i> HS 10080 EDX-2is <i>Detection Algorithm:</i> 08-01-09 <i>Auxiliary Hardware:</i> No Tray	<b>2</b> <sup>(4)</sup> (ECAC/EU expired)	21/02/2014
Smiths Detection	<b>HI-SCAN 7555 aTiX</b>	<i>Hardware:</i> HS 7555 aTiX <i>Detection Algorithm:</i> 06-41-09 <i>Auxiliary Hardware:</i> No Tray	<b>2</b> <sup>(4)</sup> (ECAC/EU expired)	05/10/2011

ECAC CEP Explosive Detection Systems (EDS) equipment (ECAC/EU expired standards (1) only). Update 30 June 2025

Manufacturer	Equipment		Standard	Notification
	Designation	Configuration <sup>(2)</sup>		
Nuctech	XT2100HS	<i>Hardware:</i> XT2100HS <i>Detection Algorithm:</i> OIS V2.0.008 Algorithm V3.1.24 <i>Auxiliary Hardware:</i> No Tray <i>CONOPS:</i> V1.0	2 <sup>(4)</sup> (ECAC/EU expired)	25/10/2016
Nuctech	XT2100HS	<i>Hardware:</i> XT2100HS DHV 1.0 XT2100HS DHV 1.1 <i>Detection Algorithm:</i> Algorithm V3.1.27 <i>Auxiliary Hardware:</i> Vanderlande Assy Carrier No. 001036-241-00002 <i>CONOPS:</i> XT2100HS CONOPS v4.0	2 <sup>(4)</sup> (ECAC/EU expired)	12/10/2017 14/12/2018 <sup>(CC)</sup> 30/09/2022 <sup>(CC)</sup>
Nuctech	XT2100Ti	<i>Hardware:</i> XT2100Ti DHV 1.0 <i>Detection Algorithms:</i> Algorithm V3.1.35 <i>Auxiliary Hardware:</i> No tray Vanderlande 001036-241-00002 <i>CONOPS:</i> XT2100Ti_CONOPS_v1.0_20181128	2 <sup>(4)</sup> (ECAC/EU expired)	25/07/2019 30/03/2022 <sup>(CE)</sup>

**ECAC CEP Explosive Detection Systems (EDS) equipment (ECAC/EU expired standards <sup>(1)</sup> only). Update 30 June 2025**

Manufacturer	Equipment		Standard	Notification
	Designation	Configuration <sup>(2)</sup>		
<p><b>Leidos</b> (Previously L3 Technologies Inc.)</p>	<p><b>MVT HR</b></p>	<p><i>Hardware:</i> 1000-10001-HR  <i>Detection Algorithm:</i> 6.5.2Eg n200  <i>Auxiliary Software:</i> 5.3.11  <i>Auxiliary Hardware:</i> No Tray</p>	<p><b>2<sup>(4)</sup></b> (ECAC/EU expired)</p>	<p>17/04/2012</p>

**Notes:**

<sup>(1)</sup> **ECAC/EU expired standard:** The use of equipment configurations meeting an expired standard is not recommended to ECAC Member States from the expiration date set out in Doc 30, Part II (Security). EU Member States shall not use equipment meeting an expired standard, in accordance with EU Regulations)

<sup>(2)</sup> Information on **configuration** was provided by the equipment manufacturer as part of the testing process.

<sup>(3)</sup> **Standard 1** for Explosive Detection Systems expired on 01 January 2014 (Ref ECAC Doc 30, Part II (Security); Ref Commission implementing Regulation (EU) 185/2010 Annex 12.4.2.2)

<sup>(4)</sup> **Standard 2** for Explosive Detection Systems expired on 01 September 2021 (Ref ECAC Doc 30, Part II (Security); Ref Commission Implementing Regulation (EU) 2015/1998 Annex 12.4.2.2, amended by Commission Implementing Regulation (EU) 2021/2551)